THE STATE

DUT 25188

1962 AUG 1

25X1

25X1

T O P S E C R E T

1.

5033

INFORMATION REGARDING 9041.

- 2. DO YOU HAVE ANY DATA THAT INDICATES YAW PROBLEM PASS AG2?
- 3. OUR PRELIMINARY INFORMATION INDICATES THAT THERE IS A SEVERE YAW PROBLEM DURING PASS A02. PLOTS OF PASS A02 SHOW A YAW CONDITION OF ABOUT 70 DEGREES. SAME SMALL IMAGE APPEARS ON FOUR FRAMES IN SEQUENCE ON FWD CAMERA; EXAMPLE, FRAMES 28, 29, 30, 31.
- 4. QUICK CHECK OF FRAMING CAMERA INDICATES THAT YAW CONDITION DOES NOT CARRY ON INTO LATER PASSES, 37, 04 ETC.
- 5. ALSO ROLL APPROXIMATELY 3 DEGREE 50° INDICATED ON FRAME 33, A02. SIEMS TO CORRECT OK LATER PASSES.
- 6. SENDING THIS INFORMATION TO FOREWARN YOU AND TO GIVE YOU LEAD-TIME FOR PONDERING.

TOPSECRET

CFN: 5033 -X 9041 YAV A02 A02 A02 A YAW 70 28 29 30 31 NOT CARRY

BT

170

25X1

